

## **APPENDIX C PHOTO LOG**

## Photo Log



**Photo 1. Reacquisition at Lima Pond using EM61 Time Domain Metal Detector, 3/7/02**



**Photo 2. Lima Pond investigation area, 3/7/02**



**Photo 3. Open path Fourier Transform Infrared Spectrometry Air Monitoring (OPFTIR) in calibration mode at Lima Pond, 4/16/02**



**Photo 4. Perimeter Depot Area Air Monitoring System (DAAMS) station at Lima Pond, 4/16/02**





**Photo 5. Miniature Chemical Agent Monitoring System (MINICAMS) sample lines and DAAMS station at Lima Pond, 4/16/02**



**Photo 6. Anomaly #1 excavation at Old Water Hole, 4/4/02**



**Photo 7. Anomaly #1 excavation at Old Water Hole, 4/3/02**



**Photo 8. MINICAMS set-up in Box Truck, 4/2/02**





**Photo 9. Scrap metal removed from excavation at Old Water Hole, 4/3/02**



**Photo 10. North end of Former Decon Area, facing south, 3/7/02**



**Photo 11. Middle of Former Decon Area, facing southeast, 3/7/02**



**Photo 12. Scrap metal removed from anomalies investigated at Former Decon Area, 4/17/02**